


CH7 Fundamentals of Dc Machine


Simple Dc machine

- It consists of a simple loop of wire rotating around a fixed O, O' axis.
- The stationary part is called stator and the rotating part is called rotor.
- The magnetic field is supplied by a magnet north pole & magnet south pole.




⊕ Induced Voltage (Generators Mode)

$$\text{Induced voltage} = (\vec{v} \times \vec{B}) \cdot \vec{L}$$



ω_m : speed of rotation



⊗ الفيض AC هو اتجاه الزاوية 90°
التي هي 90°

① Segment ab

$$e_{ba} = \int_0^{VBL} \text{ , under the pole face}$$

0 , beyond the pole edge.

angle between $\vec{V}$ & $\vec{B}$ is 90°
∴ $(\vec{V} \times \vec{B}) \cdot \vec{L}$ is zero

② Segment cd

$$e_{cd} = \begin{cases} VBL & \text{, under the pole face} \\ 0 & \text{, beyond the pole edge} \end{cases}$$

angle between $\vec{V}$ & $\vec{B}$ is 90°
∴ $(\vec{V} \times \vec{B}) \cdot \vec{L}$ is 0°

③ segment bc & da

$$e_{bc} = e_{dc} = 0 \quad \text{since } (\vec{V} \times \vec{B}) \text{ is } \perp \text{ to } \vec{L}_{bc} \text{ \& } \vec{L}_{da}$$

The Total induced Voltage is given by:

$$e_{\text{total}} = e_{ba} + e_{dc} = \begin{cases} 2VBL & \text{, under the pole face} \\ 0 & \text{, beyond the pole edge} \end{cases}$$

$$V = \omega_m r$$

$$e_{\text{Total}} = \begin{cases} 2\omega_m rLB & \text{, under the pole face} \\ 0 & \text{, beyond the pole edge} \end{cases}$$


The area of one pole surface is given by

$$A_p = \pi r L \Rightarrow r L = \frac{A_p}{\pi}$$

المجال الكلي
S. V. a. g. e. u

$$e_{\text{Total}} = \begin{cases} \frac{2}{\pi} A_p B \omega_m = \frac{2}{\pi} \phi \omega_m, & \text{under the pole face} \\ 0, & \text{beyond the pole edge} \end{cases}$$

Note: when the loop is rotating through 180° , the segment a b will become under the north pole instead of the south pole $\Rightarrow$ The direction of the induced voltage will be reversed, but the magnitude is constant.




$\Leftarrow$ This an AC Signal

Solution

The DC Voltage is obtained using Commutator segments & brushes

هذا تسمى الدارة
التي تسمى فيزي
التي تسمى فيزي
التي تسمى فيزي


تسمى الدارة
التي تسمى فيزي



Commutation Segment ϕ

Two semi-circuit conducting segments added to the end of the loop

Brushes ϕ - Fixed contacts that are set up at angle such that they will make a short circuit with the two segments when the induced voltage is zero (beyond the pole edge).



In general, the induced voltage is given by e ,



$$e_{ind} = \begin{cases} K\phi\omega_m, & \text{under the pole face} \\ 0, & \text{beyond the pole edge} \end{cases}$$

The induced voltage depends on:

- Flux of machine
- speed
- constant represent the construction of machine

Induced Torque in Motor Mode

R , to limit the starting current



$$\text{Induced Force} = C \vec{L} \times \vec{B}$$

$$\text{Torque} = \vec{r} \times \vec{F}$$

segment ab

$$F_{ab} = CLB, \quad T_{ab} = rCLB \Rightarrow T_{ab} = \int_0^{\pi} rCLB \, d\theta \quad \text{under the pole faces}$$

$$0, \quad \text{beyond the pole edges}$$

segment cd

$$F_{cd} = CLB, \quad T_{cd} = rCLB \Rightarrow T_{cd} = \int_0^{\pi} rCLB \, d\theta \quad \text{under the pole faces}$$

$$0, \quad \text{beyond the pole edges} \quad \underline{\underline{CCW}}$$

segment bc & da

$$F_{bc} = F_{da} = 0 \quad \text{since } \vec{L} \times \vec{B} = 0, \quad \left| \frac{\vec{r}}{r} = 0 \right|$$

The Total Induced Torque

$$T_{ind} = \int 2rCLB \, d\theta \quad \text{under the pole faces}$$

$$0, \quad \text{beyond the pole edges}$$

Area of one pole surface
 $A_p = \pi r^2$

$$T_{ind} = \int_0^{\omega} \frac{2}{\pi} \phi i \, d\omega \text{ under } \dots$$

In general

$$T_{ind} = K \phi i$$

which depend on

- 1) Flux
- 2) Current
- 3) Constant represent the construction of the machine

⊗ Induced Voltages


$$E_{ind} = \int_0^{\omega} K \phi \omega_m \, d\omega \text{ under the pole face}$$

o , beyond the pole edges


* Induced Torque

$$T_{ind} = \int_0^{\omega} K \phi i \, d\omega \text{ under the pole faces}$$

o , beyond the pole edges



Example



A simple rotating loop lies between curved pole faces connected to a battery and a resistor through a switch.

The resistor model, the total resistance of the battery, and the wire in the machine.

a) What happens when the switch is closed?

When the switch is closed a current will flow through the wire at starting.

$$i = \frac{V_{DC} - e_{ind}}{R}$$

At starting $\Rightarrow \omega_m = 0 \Rightarrow e_{ind} = 0 \Rightarrow i_{start} = \frac{V_{DC}}{R}$

$$\Rightarrow T_{ind, start} = k \phi i = \frac{k \phi V_{DC}}{R}$$

Newton's 2nd Law

$$T_{ind} - T_{load} = J \frac{d\omega_m}{dt} \Rightarrow \frac{d\omega_m}{dt} > 0 \Rightarrow \omega_m \uparrow$$

$$\omega_m \uparrow \Rightarrow (e_{ind} = k \phi \omega_m) \uparrow \Rightarrow i = \frac{V_{DC} - e_{ind}}{R} \downarrow$$

$\Rightarrow (T_{ind} = k \phi i) \downarrow$ until it reaches zero.

Under steady state condition

$$T_{ind} = 0 \Rightarrow i = 0$$

$$\Rightarrow e_{ind} = V_{DC} = k \phi \omega_{m,ss}$$

where $\omega_{m,ss}$ is the steady state speed of the machine.

$$k = \frac{2}{\pi} \quad (\text{one loop})$$

a) what is the machine Maximum starting current?

b) what is the steady state angular velocity at No Load?

$$I_{\text{start}} = \frac{V_{DC}}{R} = \frac{120}{0.3} = 400 \text{ A}$$

$$i = 0 \Rightarrow V_{DC} = e_{\text{ind}} \Rightarrow 120 = k \phi \omega_{ms}$$

$$120 = \frac{2}{\pi} \phi \omega_{ms}$$

$$\phi = BA = (\pi n L)(B) \Rightarrow 120 = \left(\frac{2}{\pi}\right) (\pi n L) (B) \omega_{ms}$$

$$\omega_m = 480 \text{ rad/s}$$

c) Suppose a load is attached to the loop, and the Resulting Load Torque is $10 \text{ N}\cdot\text{m}$, what would the new steady state speed? How much power supplied to the shaft of the machine? How much power is being supplied by the battery? Is this machine a motor or generator?

$$T_{\text{ind}} - T_{\text{load}} = J \frac{d\omega_m}{dt} \Rightarrow \omega_m \downarrow \Rightarrow e_{\text{ind}} = k \phi \omega_m \downarrow \Rightarrow i \uparrow$$

$$\Rightarrow T_{\text{ind}} = k \phi i \uparrow \text{ until it reaches } T_{\text{load}} = \frac{J d\omega_m}{dt} = 0$$

$$\omega_m = \omega_{m,ss} < \omega_{m,ss}$$

$$T_{\text{ind}} = (2nLB)i \Rightarrow i = 40 \text{ A}$$

$$e_{\text{ind}} = V_{DC} - Ri \Rightarrow e_{\text{ind}} = 108$$

$$108 = (2nLB) \omega_{m,ss} \Rightarrow \omega_{m,ss} = 432 \text{ rad/s}$$

$$P_m = T_{\text{load}} \omega_{m,ss} = (10)(432) = 4320 \text{ W}$$

$$P_{\text{battery}} = (120)(40) = 4800$$

Motor, since the speed decreases

- d) Suppose the machine is again unloaded and a torque of 7.5 Nm is applied to the shaft in the direction of rotation, what is the steady ss speed? Is this machine motor or generator?

$$\begin{aligned} T_{\text{ind}} - T_{\text{load}} &= \frac{J d\omega_m}{dt} > 0 \Rightarrow \omega_m \uparrow \Rightarrow e_{\text{ind}} \uparrow > V_{\text{dc}} \\ T_{\text{load}} &< 0 \end{aligned}$$

$$\begin{aligned} |\omega| \uparrow &\Rightarrow |T_{\text{ind}}| \uparrow \text{ until it reaches } T_{\text{applied}} \\ \Rightarrow \frac{J d\omega_m}{dt} &= 0 \Rightarrow \omega_m = \omega_{\text{ss}} > \omega_{\text{mss}} \end{aligned}$$

$$T_{\text{ind}} = 7.5 = 2\pi L B i \Rightarrow \boxed{i = 30 \text{ A}} \text{ in opposite direction}$$

$$e_{\text{ind}} = V_{\text{dc}} + R i \Rightarrow \boxed{e_{\text{ind}} = 129 \text{ V}}$$

$$129 = 2\pi L B \omega_{\text{mss}} \Rightarrow \omega_{\text{mss}} = 516 \text{ rad/s}$$

"generation"