



Operating principle


- The field current produces the rotor magnetic field  $\vec{B}_r$ .
- A set of 3 $\phi$  voltages is applied to the stator windings which produces a set of 3 $\phi$  currents to flow the stator windings.
- The rotor current will produce  $\vec{B}$ , which rotates at  $\omega_s$ .
- The rotor is rotating by some external means to obtain a magnetic locking between the rotor & stator poles, and then produces a continuous induced torque ( $T_{ind} = K \vec{B}_r \times \vec{B}_s$ )



$$P = 2, f = 50 \text{ Hz}$$

$$\omega_s = \frac{120}{P} f$$

$$= 3000 \text{ RPM}$$

Equivalent Circuit (Per. phase)

$R_A$ : armature resistance  
 $X_s$ : synchronous reactance  
 $X_s = X_A + X$   
 $\downarrow \quad \downarrow$   
 Reactance of stator winding    Reactance of armature reaction

$V_\phi$  : Phase voltage.

Y-connected  $\rightarrow V_T = \sqrt{3} V_\phi$

$\Delta$ -connected  $\rightarrow V_T = V_\phi$

$$E_A = K \phi \omega_s$$

↓  
Induced voltage

Back EMF  
EMF


KVL in the armature circuit

$$\vec{E}_A = \vec{V}_\phi - jX_s \vec{I}_A - R_A \vec{I}_A$$

OR  $\vec{V}_\phi = \vec{E}_A + R_A \vec{I}_A + jX_s \vec{I}_A$

⊗ Phasor Diagrams

$\theta$  : PF angle



$$T_{ind} = K B_r \times B_s \approx K \vec{B}_r \times \vec{B}_{act}$$

$$T_{ind} = K B_r B_{act} \sin \delta$$


$\delta$  : Torque angle

$\vec{B}_r$  : ~~armature~~ corresponds to  $E_A$


$\vec{B}_{act}$  : corresponds to  $\vec{V}_\phi$

$\vec{B}_s \propto (-jX_s \vec{I}_A)$


"Armature reaction"



"generator"



### Torque - speed characteristics



Pull-out Torque is the maximum operating torque of synchronous motor

$$T_{max} = (2.5 - 3) T_r$$

$$\text{Speed Regulation} = SR = \frac{M_{NL} - Y_{FI}}{Y_{FI}} \times 100\%$$

$$Y_{NL} = Y_{FI} = Y_T = \frac{120}{P} \%$$

$$SR = 0\%$$

Torque equation

$$T_{ind} = \frac{3 V_\phi E_A \sin \delta}{X_s \omega_s} \Rightarrow T_{max} = \frac{3 V_\phi E_A}{X_s} \quad \delta = 90^\circ \text{ max}$$

If  $T_{load} > T_{max} \Rightarrow$  The motor will lose synchronism  
 $\Rightarrow$  "slipping pole phenomenon"


⊗ Effect of load changes

$$T_{ind} = \frac{3 V_\phi E_A}{X_s \omega_s} \sin \delta$$

$$T_{ind} - T_{load} = J \frac{d\omega_m}{dt} \quad \text{inertia}$$

$T_{load} \uparrow \Rightarrow \omega_m \downarrow \Rightarrow \delta \uparrow \Rightarrow T_{ind} \uparrow \Rightarrow \omega_m \uparrow$  until it reaches synchronous speed


⊗ Phasor



Vid 10


$T_{ind} \propto I_A \cos \phi$  and  $I_A \cos \phi$  is the component of  $I_A$  in phase with  $V_0$ .  
 $I_A \cos \phi$  is the component of  $I_A$  in phase with  $V_0$ .

$$P \propto I_A \cos \phi$$



Effect of Load changes

$$T_{ind} = \frac{3 V_0 E_A \sin \delta}{X_s \omega_s}$$



$$T_{ind} - T_{load} = \frac{J d\omega_r}{dt} \quad \omega_r = \text{Rotor speed}$$

$T_{load} \uparrow \Rightarrow \omega_r \downarrow \Rightarrow \delta \uparrow \Rightarrow T_{ind} \Rightarrow \omega_r \uparrow$  until it reaches  $\omega_s$ , but at large  $\delta$

Load  $\uparrow \Rightarrow$  The PF becomes less leading  $\rightarrow$  unity  $\rightarrow$  lagging  $\rightarrow$  more lagging

اثر التغير في  $P$  على  $\phi$  و  $I_A$  و  $E_A$

Effect of  $I_F$  changes


Assume  $P$  is constant

$$P = \frac{3V_\phi E_A \sin \delta}{X_s} = 3V_\phi I_A \cos \theta = \text{Constant}$$

$$E_A \sin \delta = \text{Constant} \quad \& \quad I_A \cos \theta = \text{Constant}$$


لذا

Try to increase  $I_F$  ( $E_A$ )



$$E_A = k \phi \omega_s$$


$I_F \uparrow \Rightarrow E_A \uparrow \Rightarrow$  PF becomes less lagging  $\rightarrow$  moving  $\rightarrow$  leading  
 $\rightarrow$  More & More leading



$$S \downarrow = V I \downarrow$$

$$S = \sqrt{P^2 + Q^2}$$

## V-curves of synchronous Motors.



$$P_3 > P_1 > P_2$$

its a data Represent  
the armature current  
and field current

when  $E_A \cos \delta < V_\phi \Rightarrow$  Lagging PF  $\Rightarrow$  Q is consumed  
 $\Rightarrow$  under-excited process


when  $E_A \cos \delta > V_\phi \Rightarrow$  PF is Leading  
 $\Rightarrow$  Q is supplied  
 $\Rightarrow$  over-excited process

## Synchronous Condenser or Synchronous Capacitor


Its a synchronous motor without its shaft operated at no-load ( $P=0$ ) & over excited (Q is supplied) it was used historically a power factor correction Device.

$$P=0 \Rightarrow P = \frac{3 V_\phi E_A \sin \delta}{X_s} = 3 V_\phi I_A \cos \theta$$

$$P=0 \Rightarrow \delta=0 \text{ or } \theta=90^\circ$$




Power Factor correction  
can be achieved by :-



- 1) Synchronous Condenser
- 2) Static Capacitors
- 3) Using power electronics


③



Example 208V, 45KVA, 0.8 PF leading,  $\Delta$ -connected, 60Hz, synchronous machine has  $X_s = 2.5 \Omega$  &  $R_A = 0$ . Its friction and windage losses are 1.5kW, & its core losses are 1kW. Initially the shaft is ~~supplying~~ supplying a 15 hp load, and the motor PF is 0.8 leading.  
1hp = 746W

a) Find the values of  $\vec{I}_\phi$ ,  $I_L$  &  $\vec{E}_A$  ?

b) Assume that shaft load is now increased to 30 hp, Find  $\vec{I}_\phi$ ,  $I_L$  &  $\vec{E}_A$ , what is the new motor PF ?



KVL in the Armature Circuit

$$208 \angle 0^\circ = j2.5 \vec{I}_a + \vec{E}_A$$

$$P_{out} = (15)(746) = 11.19 \text{ kW}$$

$$P_{in} = 11.19 + 2.5 = 13.69 \text{ kW} = 3 V_\phi I_\phi \text{ PF}$$

$$I_\phi = \frac{(13.69 \times 10^3)}{(3)(208)(0.8)} \angle + \cos^{-1}(0.8) = 27.4 \angle 36.87^\circ \text{ A}$$

$$\vec{E}_A = 255 \angle -12.4^\circ \text{ V}$$

$$I_L = \sqrt{3} I_\phi = 47.5 \text{ A}$$

b)

$$208 \angle 0^\circ = j2.5 \vec{I}_a + \vec{E}_A \quad \text{KVL} = E_A = \text{constant}$$

$$P_{in} = \frac{3 V_\phi E_A \sin \delta}{X_s}$$

$$P_{in} = (30)(746) + 2.5 \times 10^3 = 24.82 \text{ kW}$$

$$24.82 \times 10^3 = \frac{(3)(208)(255) \sin \delta'}{2.5}$$

$$\delta' = 23^\circ$$

$$\vec{E}_A = 255 \angle -23^\circ \text{ V}$$


$$\vec{I}_\phi = \frac{208 - 255 \angle -23^\circ}{j2.5} = 41.2 \angle 15^\circ$$

$$PF_{\text{new}} = \cos(0^\circ - 15^\circ) = 0.966 \angle \text{Lead}$$

Wpss and @ Wpss  
PF

### Starting of synchronous Motor

Assume that a 50Hz power is supplied to a two poles synchronous Motor



$\omega_s = \text{synchronous speed}$

it will vibrate heavily  $\Rightarrow$  overheated

### Method to start the synchronous Motor

① Using external prime mover e.

- Run the machines as generation using the prime mover.
- Increase the motor speed up to  $\omega_s$

- Connect the prime mover.

② Using damper or amortisseur windings


This method will start up the synchronous motor like 3 $\phi$  induction motor

③ Reducing the electric frequency

$$U_s = \frac{120}{p} f_e$$


Motors are (Synchronous)   
 Load  $\rightarrow$  from 1/3400

when  $f_e$  is small  $\Rightarrow$  the speed of  $B_s$ , will be also small ( $n_s = \frac{120}{p} f_e$ )   
 $\Rightarrow$  The rotor can ~~accelerate~~ accelerate and lock in with  $B_s$ .   
 $\Rightarrow$  when the motor is started increase the electric frequency gradually up to its normal value.




$$V_\phi \approx E_A = K \phi \omega_s \propto f_e$$

$\phi \propto V/f_e \Rightarrow$  Two voltage must decrease with  $f_e$  by the same factor to keep  $\phi$  constant & not let it saturated.



$$\frac{V}{f} = \text{constant}$$

V V F Drive



So you can work at Rated Torque at all speeds

✓ ✓ ✓ ✓ ✓ ✓  
CH5 problems 1, 2, 3, 7, 9, 10, 14, 17, 18, 19