Measurements and Uncertainties

Sources of excores: 1- Choice of instruments 2-The Expirementer 3-The Environment 4-The way The expirement is done 5-The way The physical quantity is measured

· A measurement can never be take without any error But it can be estimated when all extrems are very small

Je Mays's locking perpendicularly . عدم البدع مم الترام العجم uncalibrated in Sen He a safeti app estates Instrument

un certainty in a measurement (we estimate it)

om = on : standard deviation of

Precision) and (Accuracy)

9.82 ± 05 less 9.8 ±0.1 Mover precise

> Systematic ercco ercor

Less Accuracy Morer Accuracy

Exp: True Value: 9.86 XX=9.8 Z + ON More According XB = 10.1 + 0.4 > less Acurelle

Alaa Ebaiwi

Discrepancy test accepted Instaccepted * True Value X * Result X ± DX - Steps: 1- 0 = |X-X| 2-2* DX 3-If DJ2DX not accepted & D<2DX accepted significant figures • حي الله عام المعنوبة التي عكرن عدّها 900: 3 = 900: 4 sig Tigrificant should always be 1 sig figure unless the leading digit was one Then we keep The digit ofter Exp 0.12320.12 0.16=20 or 1.6 Rounding Rules :-· any number less I han 5 & we fix The sig fig more ~ 5 we wound The last signifup · If it was 5: Exp 3,5 -> 40 applicant 40 0.7251 > 0.73

(Valuez * Addition and substraction

The no with the fement deciment places limits the number of decimal places in The result

* Multiplication and division

· we find how much of sig fig There is in The numbers If ultiplied: The less controls The result

drie 15

· √(3)= 3.782 ~ 3.8 12.4+10.2 = \12.6 = 3.5/49 asis viet

asin (24) = (0.406)asin (24) = (0.406)

(os (70) = 0.342

(un Corchainity,)

* Addition and substraction

R=X±y DR= DX+Dy: general rule

* Constant Multipliers.

R= ax +by AR= axx + bay

But if a and b are not coust Then DR= a DX + XBa + b Dy + Dbi

* Multiplication and clinision

A = y A + X Ay

Care 2 values

A = yAX + XAY

for more Than 2 values

Slea Etaiwi

عن طرفه 188 - 27

Alaa Etaiwi